

An aerial photograph of a port facility. A large cargo ship is docked at a pier. The port area includes various industrial buildings, storage tanks, and a network of roads. The surrounding landscape is a mix of green fields and some developed areas. The text "Commonwealth Ports Authority" is overlaid in white, semi-transparent font.

Commonwealth Ports Authority

Super Typhoon Sinlaku – April 2026

Super Typhoon Bavi – July 2026

Rota West Harbor Marina



Marina Entrance



Marina Slips



Marina Slips

Rota West Harbor – Berths 1 and 2



Berth 1



CPA Office at Berth 2



Berth 1

Rota West Harbor – Berths 1 and 2



Large Cavity at Berth 2



Washed Up Rocks at Berth 1



Berth 1

Rota West Harbor Recovery after Super Typhoon Bavi



Port of Saipan – Dock Side



Storm Debris



Compromised Chain Link Fence



Damaged Dock Lights

Port of Saipan – Capsized Vessels



Berth 103 – Sunken Vessel



Delta Dock



North Sea Plane Ramp

Port of Saipan – Delta Dock & Echo Dock Damages



Delta Dock



Delta Dock



Echo Dock

Port of Tinian – West Quay



West Quay – RoRo Ramp



End of West Quay



End of West Quay – South Facing

Port of Tinian - Marina



Storm-Damaged Steps



Storm-Caused Erosion



Compromised Pavement